

	Live life faster		
Competitor	Finding	Rule Breach	Penalty to be Applied
Heremana	The Clerk of the Course finds that: Car 909 & 910 Fuelling rig does not comply with series accredited articles, the shut off	This is a breach of rule: Series Accredited Articles Part 6 Article	The Clerk of the Course rules: Series Accredited Articles Part 7 Article 1.2, P7.11 Applies and you are fined
Malmezac &	valve is not auto closing.	5.4.3 (d)	\$300.
Francios Beziac			
Heremana	The Clerk of the Course finds that: Car 910 pit crew have not had the correct PPE as per Accredited Articles. There were no	This is a breach of rule: Series Accredited Articles Part 6 Article 4.4	The Clerk of the Course rules: Series Accredited Articles Part 7 Article 1.2, P7.4 Applies. Drive through
Malmezac &	gloves on the personnel stationed on the refueler shut off valve		penalty issued via Race Radio and displayed on signalling board and flag at start line: issued @ 15:45 hours
Francios Beziac			and Complied 15:47 hours
Scott Smith	The Clerk of the Course finds that: Car 191 has failed to complete the required Pit Stop. As observed by Judge of Fact The	This is a breach of rule: Series Accredited Articles Part 5 Article 1.6	The Clerk of the Course rules: Series Accredited Articles Part 7 Article 1.2, P7.1 Applies and Car 191 is
	vehicle only remained stationary for 41 seconds.		excluded from the Race Results
	The Clerk of the Course finds that: You have not taken part in either of the practice or qualifying sessions that are required	This is a breach of rule: Series Accredited Articles Part 5 Article	The Clerk of the Course rules: NSC 4 Applies and you are fined \$100.
Jono Lester	under the Accredited articles. Which you have acknowledged this as being correct, as due to practicing on Friday thought	1.2.1	
	that this was sufficient, however this was outside of the permit for the event		