

	Live life faster		
Competitor	Finding	Rule Breach	Penalty to be Applied
	The Race Director finds that: Was reported by Toyota Gazoo Racing New Zealand as having	This is a breach of rule: 2023 -2024 Toyota 86 Championship Articles.	Penalty to be applied: Articles of 2023-2024 Toyota 86 Championship Penalty A2.40 applies. Summer
Summer Rintoule	exceeded testing limits as set down in the Championship	Article 6.2(b).	Rintoule Car #87 is to have 34 Championship points removed from her total Championship points tally.
	Articles 6.2(b). Car 87 totalling 1634 kilometres total.		One point per kilometre over the allowance.
	This is a breach of Article 6.2(b).		
	A hearing was held with the Competitor and the breach was established.		
Thomas Bewley	The Race Director finds that: Track limits were exceeded at Turn 4 where the vehicle left the	This is a breach of rule: Appendix Four Schedule Z Article 13.2.	The Race Director rules: Articles of 2023-2024 Toyota 86 Championship Penalty A2.22 applies. Car #4
	circuit with all four tyres. This was reported by Series		Driver: Thomas Bewley
	Driving Standards Observer Rowan Sheppard.		Laps 3 and 4 are invalidated. (Deleted) Additionally one Championship demerit point is applied. You now
	This is a breach of Appendix Four Schedule Z 13.2.		have 5 points.
	This occurred on Lap 3.		
	A Race Radio call was made at the time.		
Harry Townshend		This is a breach of rule: Appendix Four Schedule Z Article 13.2.	The Race Director rules: Articles of 2023-2024 Toyota 86 Championship Penalty A2.22 applies Driver: Harry
	Session: Qualifying	**	Townshend
	Track limits were exceeded at Turn 4 where the vehicle left the circuit with all four tyres. This was		Laps 3 and 4 are invalidated. (Deleted) Additionally one Championship demerit point is applied. You now
	reported by Series		have 1 point.
	Driving Standards Observer Rowan Sheppard.		- Lance 2 points
	This is a breach of Appendix Four Schedule Z 13.2.		
	This occurred on Lap 3.		
	A Race Radio call was made at the time.		
	The Race Director finds that: Car# 75	This is a breach of rule: Appendix Four Schedule Z Article 13.2.	The Race Director rules: Articles of 2023-2024 Toyota 86 Championship Penalty A2.22 applies. Car #75
	Driver: Tayler Bryant	This is a second of Tute. Appendix Four Schedule 2 Article 13.2.	Driver: Tayler Bryant
	Session: Qualifying		Laps 3 and 4 are invalidated. (Deleted) Additionally one Championship demerit point is applied. You now
	Track limits were exceeded at Turn 4 where the vehicle left the circuit with all four tyres. This was		have 4 points.
Tayler Bryant	reported by Series		nave 4 points.
Tayler bryant			
	Driving Standards Observer Rowan Sheppard.		
	This is a breach of Appendix Four Schedule Z 13.2.		
	This occurred on Lap 3.		
	A Race Radio call was made at the time.	This is a base of male. Assessed in Farm Cabadada 7 Anticle 12 2	The Barr Birrate and a settler of 2022 2024 Tourston OC Characters bir Barrelto A2 22 and in Control
	The Race Director finds that: Car# 81	This is a breach of rule: Appendix Four Schedule Z Article 13.2.	The Race Director rules: Articles of 2023-2024 Toyota 86 Championship Penalty A2.22 applies. Car #81
	Driver: Cormac Murphy		Driver: Cormac Murphy
	Session: Qualifying		Laps 5 and 6 are invalidated. (Deleted) Additionally one Championship demerit point is applied. You now
	Track limits were exceeded at Turn 4 where the vehicle left the circuit with all four tyres. This was		have 6 points.
Cormac Murphy	reported by Series		As you have 6 points you are moved six grid places back for the next race. Championship Articles – 9.3.
	Driving Standards Observer Rowan Sheppard.		
	This is a breach of Appendix Four Schedule Z 13.2.		
	This occurred on Lap 5.		
	A Race Radio call was made at the time.		
William Morton	The Deputy Race Director finds that: Car #11	This is a breach of rule: Articles of 2023-2024 Toyota 86 Championship	The Race Director rules: Articles of 2023-2024 Toyota 86 Championship Penalty A2.19 applies. Car #11
	Driver: William Morton	Penalty A2.19 applies.	Driver: William Morton will be moved three (3) grid places back on the starting grid for Race 1. 2 demerit
	Session: Qualifying		point are
	After a hearing between the Deputy Race Director, Series DSO and competitors and reviewing in		applied. You now have 4 demerit points.
	car footage, it is found		
	that Car #11 made contact with Car #73 at Turn 12. This had a negative effect on Car #73.		
	This is a breach of Appendix Four Schedule Z Article 15.3		
Ben Stewart	The Race Director finds that: Car# 33	This is a breach of rule: Schedule TR Article 9.3.1(2)	The Race Director rules: Articles of the 2023/24 Toyota 86 Championship Penalty A2.9 applies. Car# 33
	Driver: Ben Stewart		Driver: Ben Stewart is fined a sum of \$1000. Excluded from Qualifying and has his Competition Licence
	Session: Qualifying		Endorsed for a period of 6 months. Ending October 19 2024 at 5pm.
	Judge of Fact Tech Weights and Measures Justin Scelly reports that during post qualifying checks		
	Car 33 has been found to		
	have a rear camber measurement of, Left side 2.7 degrees negative and Right side 2.5 degrees		
	negative.		
	This is a breach of Schedule TR 86 Technical Regulations article 9.3.1(2). Maximum camber of 2.2		
	degrees negative.		
Tom Bewley, Thomas Mallard & Hunter Robb	The Race Director finds that: After a hearing with the Race Directors for Toyota 86, the Series	This is a breach of rule: No breach established.	The Race Director rules: No penalty imposed.
	Driving Standards Observer and the Drivers, which		
	involved viewing video footage from numerous cars. It is determined that no one driver can be		
	wholly or predominantly		
	held responsible for the incident at Turn 5 Lap 1.		
	No further action is to be taken.		
	The farther determine to be taken.		
	You were verbally advised of this fact at this time.		
1	TTOU WELE VELDALIV AUVISEU OF LITIS TALL AL LITIS LITIE.	I	ı

	The Race Director finds that: After a hearing with the Race Directors for Toyota 86, the Series	This is a breach of rule: No breach established.	The Race Director rules: No +A13+B11:D14+A10:D1+A1:D14
	Driving Standards Observer and the Driver, which		
	involved viewing video footage from numerous cars and data from Car 81 It is determined that an		
	external factor played a		
Cormac Murphy	part in the incident which was outside of the drivers control. Namely oil on the circuit being		
	dropped from a car involved		
	in an incident at the prior corner. Car 81 failed to finish the race.		
	No further action is to be taken.		
	You were verbally advised of this fact at this time.		