

TECHNICAL INSPECTION REPORT

Formula First Car # 14 – Billy Frazer

26th October 2018

A request to break the Championship Seals was received from Car 14, Billy Frazer to allow maintenance.

An inspection as detailed below was carried out on Friday 26th October at Daytona raceway, Palmerston North.

The cylinder head to crankcase seal was noted as Serial Number MSNZ10978. This matched the recorded seal number in the Logbook on 21st October at Round One and the Seal Register.

The seal was removed and the cylinder heads removed. The following inspections were carried out:

Article #	Check	Tolerance	Measurement	Pass/Fail
Sch V 9.2.3	Combustion chamber volume	39cc minimum	39.9cc	Pass
Sch V 9.2.5	Inlet valve diameter	Max dia. 31.5mm	31.47mm	Pass
Sch V 9.2.5	Exhaust valve diameter	Max dia. 30.0mm	29.89mm	Pass
Sch V 9.2.1(b)	Intake port diameter	Max dia. 29.0mm	28.89mm	Pass
Sch V 9.2.4	Exhaust port diameter	Max dia. 33mm	32.85mm	Pass
Sch V 9.3.1	Cylinder bore	Max bore 77.5mm	76.89mm	Pass
Sch V 9.3.6	Engine stroke	64.0mm +/- 0.02	64.01mm	Pass
Sch V 9.3.5	Piston deck height	20ft/lbs	0.0ft/lbs	Pass

All items checked were found within tolerances specific in Schedule V.

Terry Carkeek
Technical Officer
Licence 934300Y